





SHARP MFP POWER REQUIREMENTS

<u>Sharp B&W Models</u>	<u>Sharp Color Models</u>	<u>Power Supply</u>	<u>Outlet Configuration</u>
AR-M162E AR-M207E AR-208D FO-2080 MX-M200D / MX-M232D AR-M257 AR-M317 MX-M260 MX-M310 DX-B350P / DX-B450P MX-B400P MX-B402 / MX-B402SC MX-M283N / MX-M363N / MX-M453N / MX-M503N MX-M350N, MX-M450N MX-M350U, MX-M450U AR-M237 / M277 AR-M355 / M455	MX-2310U DX-C310 MX/DX-C311 DX-C400 MX-C400P MX/DX-C401 MX-C4025C MX-2600N / MX-3100N MX-2610N / MX-3110N / MX-3610N MX-2300N / MX-2700N MX-3501N / MX-4501N	120 VAC, 60 Hz, 15 AMP, Dedicated Circuit, No Extension Cords, NEMA 5-15 Receptacle	
MX-M550N MX-M620N MX-M700N MX-M550 / MX-M620 / MX-M700 MX-M623U/N MX-M753U/N	MX-4001N / MX-4101N / MX-5001N MX-4110N / MX-4111N / MX-5110N / MX-5111N MX-5500N / MX-6201N / MX-7001N MX-6200N / MX-7000N	120 VAC, 60 Hz, 20 AMP, Dedicated Circuit, No Extension Cords, NEMA 5-20 Receptacle	
MX-M850 / MX-M950 / MX-M1100		220 VAC, 60 Hz, 20 AMP, Dedicated Circuit, No Extension Cords, NEMA 6-20 Receptacle	