

When Customizing Home Screen Icon Names The Names go To Factory Default When User Authentication is Enabled

May 27, 2015

Sharp Technical Tip

Models: MX-2640N/MX-3140N/MX-3640N

Cause: Added functionality to new models for user authentication

Solution: See PDF attachment (at the bottom of the page)

Les Olson Company Knowledge Base

<http://www.kb.lesolson.com/InstantKB2016/KnowledgebaseArticle50609.aspx>