




SHARP MFP POWER REQUIREMENTS

<u>Sharp B&W Models</u>	<u>Sharp Color Models</u>	<u>Power Supply</u>	<u>Outlet Configuration</u>
DX-B350P / DX-B450P FO-2081 MX-B201D MX-B402 / MX-B402SC MX-M232D MX-M264N / MX-M314N / MX-M354N MX-M283N / MX-M363N / MX-M453N / MX-M503N MX-M364N / MX-M464N / MX-M564N MX-M365N / MX-M465N / MX-M565N	MX-2615N / MX-3115N MX-2616N / MX-3116N MX-2610N / MX-3110N / MX-3610N MX-2640N / MX-3140N / MX-3640N MX-C300P / MX-C250 / MX-C300W / MX-C301W MX-C312 MX-C402SC	AR-D5133NT or MX-PCS-15D 120 VAC, 60 Hz, 15 AMP Dedicated Circuit No Extension Cords NEMA 5-15R Receptacle	
<u>Sharp B&W Models</u>	<u>Sharp Color Models</u>	<u>Power Supply</u>	<u>Outlet Configuration</u>
MX-M623U / MX-M623N / MX-M753U / MX-M753N MX-M654N / MX-M754N	MX-4110N / MX-4111N / MX-5110N / MX-5111N MX-4140N / MX-4141N / MX-5140N / MX-5141N	AR-D5143NT or MX-PCS-20D 120 VAC, 60 Hz, 20 AMP Dedicated Circuit No Extension Cords NEMA 5-20R Receptacle	
<u>Sharp B&W Models</u>	<u>Sharp Color Models</u>	<u>Power Supply</u>	<u>Outlet Configuration</u>
MX-M850 / MX-M950 / MX-M1100 MX-M904 / MX-M1054 / MX-M1204	MX-6240N / MX-7240N MX-6500N / MX-7500N	MX-E524ZNT or MX-PCS-20820D 208 VAC, 60 Hz, 20 AMP Dedicated Circuit No Extension Cords NEMA 6-20R Receptacle	